



LAB FLOOR REPAIR

AURORA, IL

PROJECT HIGHLIGHTS:

Precision, cleanliness, and experience is required to execute highly sensitive lab spaces. A repeat client required repairs to address debris buildup from an expansion joint shift that threatened the flooring and workspace environment.

To protect sensitive equipment and maintain clean workspaces, our Service Division enclosed the impacted area to contain dust and debris during construction. Our team carefully removed the damaged vinyl composition tile (VCT), chipped out old concrete for proper adhesion, and poured fresh concrete. Once the foundation was set, new VCT was seamlessly installed in the affected areas, allowing the client to avoid a full floor replacement.

Clarion's cost-effective, controlled solution restored the flooring's stability and appearance, balancing quality repair with significant cost savings for the client.

INDUSTRY:

Global Manufacturing / Lab

SERVICES:

1. Concrete Expansion Repair
2. LVT Replacement