



DEMISING WALL REPAIR

DES PLAINES, IL

PROJECT HIGHLIGHTS:

This project involved an emergency wall repair for a food-grade warehouse, where a forklift collision tore down a demising wall, disrupting operations. Clarion's Service Division quickly stabilized the area, ensuring the warehouse could continue operations safely. Recognizing Clarion as a trusted partner (who had completed the original build-out), the client reached out for assistance. Rather than repairing the wall, the client opted to transform it into a permanent pass-through, enhancing the facility's functionality while offering a cost-effective solution.

INDUSTRY: Industrial Warehouse

SERVICES:

1. Wall Repair
2. Stabilize and Secure Hazard